

State of Utah

Department of Natural Resources

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA Division Director $\begin{array}{c} {\rm JON~M.~HUNTSMAN,~JR.} \\ {\rm \it Governor} \end{array}$

GARY R. HERBERT Lieutenant Governor

| Representatives Present During the Inspection: | | | | |
|--|---|--|--|--|
| Company | Rusty Netz Environmental Coordinator | | | |
| Company | Michael Blakey Plant Manager | | | |
| Other | S. Scott Carlson President | | | |
| OGM | Karl Houskeeper Environmental Scientist III | | | |

Inspection Report

| Permit Number: | C0070035 | | |
|------------------|--------------------------|--|--|
| Inspection Type: | COMPLETE | | |
| Inspection Date: | Wednesday, June 22, 2005 | | |
| Start Date/Time: | 6/22/2005 1:00:00 PM | | |
| End Date/Time: | 6/22/2005 3:00:00 PM | | |
| Last Inspection: | Wednesday, May 25, 2005 | | |

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Partly Cloudy. Temp 82 Deg F
InspectionID Report Number: 644

Accepted by: pgrubaug 6/27/2005

Permitee: SUNNYSIDE COGENERATION ASSOCIATES
Operator: SUNNYSIDE COGENERATION ASSOCIATES

Site: SUNNYSIDE REFUSE & SLURRY

Address: PO BOX 159, SUNNYSIDE UT 84539

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

| Current Acreages | Mineral Ownership | Types of Operations | | |
|------------------------|-------------------|---------------------|--|--|
| 210 00 Total Downstand | | | | |

| 310.00 | Total Permitted | ☐ Federal | ☐ Underground |
|--------|------------------------|--------------|-----------------------|
| 202.00 | Total Disturbed | ☐ State | Surface |
| | Phase I | County | Loadout |
| | Phase II | ✓ Fee | Processing |
| | Phase III | Other | ✓ Reprocessing |

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

There are no pending compliance actions. The only permit condition currently in place is that the permittee must submit all water monitoring data in an electronic format to the Division's web site. The permittee is complying with this stipulation.

Permit actions: Task #2223 Expansion of Excess Disposal Area #2. Task #2252 Change in Resident Agent.

Inspector's Signature Date Thursday, June 23, 2005

Karl Houskeeper, Environmental Scientist III

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0070035 Inspection Type: COMPLETE

Inspection Date: Wednesday, June 22, 2005

Page 2 of 4

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable. b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
 Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

| | | Evaluated | Not Applicable | Comment | Enforcement |
|------|---|-----------|----------------|----------|-------------|
| 1. | Permits, Change, Transfer, Renewal, Sale | ✓ | | ✓ | |
| 2. | Signs and Markers | ✓ | | ✓ | |
| 3. | Topsoil | ✓ | | | |
| 4.a | Hydrologic Balance: Diversions | ✓ | | | |
| 4.b | Hydrologic Balance: Sediment Ponds and Impoundments | ~ | | ✓ | |
| 4.c | Hydrologic Balance: Other Sediment Control Measures | ~ | | | |
| 4.d | Hydrologic Balance: Water Monitoring | ✓ | | ✓ | |
| 4.e | Hydrologic Balance: Effluent Limitations | ✓ | | ✓ | |
| 5. | Explosives | | ~ | | |
| 6. | Disposal of Excess Spoil, Fills, Benches | ✓ | | ✓ | |
| 7. | Coal Mine Waste, Refuse Piles, Impoundments | ✓ | | ✓ | |
| 8. | Noncoal Waste | ✓ | | | |
| 9. | Protection of Fish, Wildlife and Related Environmental Issues | ✓ | | | |
| 10. | Slides and Other Damage | ✓ | | | |
| 11. | Contemporaneous Reclamation | ✓ | | | |
| 12. | Backfilling And Grading | ✓ | | | |
| 13. | Revegetation | ✓ | | | |
| 14. | Subsidence Control | ✓ | | | |
| 15. | Cessation of Operations | ✓ | | | |
| 16.8 | a Roads: Construction, Maintenance, Surfacing | ✓ | | | |
| 16.k | Roads: Drainage Controls | ~ | | | |
| 17. | Other Transportation Facilities | ✓ | | | |
| 18. | Support Facilities, Utility Installations | ✓ | | | |
| 19. | AVS Check | ✓ | | ✓ | |
| 20. | Air Quality Permit | ✓ | | ✓ | |
| 21. | Bonding and Insurance | ✓ | | ✓ | |
| 22. | Other | | | | |

Permit Number: C0070035 Inspection Type: COMPLETE

Inspection Date: Wednesday, June 22, 2005 Page 3 of 4

1. Permits, Change, Transfer, Renewal, Sale

There are no pending compliance actions. The only permit condition currently in place is that the permittee must submit all water monitoring data in an electronic format to the Division's web site. The permittee is complying with this stipulation.

Permit actions: Task #2223 Expansion of Excess Disposal Area #2.

Task #2252 Change in Resident Agent.

The following permits were reviewed:

- -Mining permit C/007/035 issued February 4, 2003 and expires February 4, 2008.
- -UPDES permit #UT0024759 effective August 1, 2002 and expires midnight July 31, 2007.
- -Air Quality Permit DAQO-702038-02 issued November 1, 2002, remains in effect.
- -SPCC plan is only applicable to plant site which is not within the permit area.
- -Certificate of Insurance effective 08/01/2004 and terminates 08/01/2005.
- -Reclamation agreement is dated December 1996 and signed by both parties.

2. Signs and Markers

The mine ID sign is located adjacent to the tipple on a light pole. The MSHA Refuse and Impoundment signs were also checked during the inspection and contained the required information.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The first quarter 2005 inspection of the sediment ponds was done in conjunction with the Division complete (March 25, 2005) inspection by Scott Carlson a registered professional engineer in the State of Utah. Mr. Carlson compiled a report dated April 8, 2005. The second quarter 2005 inspection of the sediment ponds was done in conjunction with this complete inspection. A report of the findings will be generated from the inspection.

4.d Hydrologic Balance: Water Monitoring

First quarter 2005 water monitoring is in the EDI website and uploaded. Water monitoring is current.

4.e Hydrologic Balance: Effluent Limitations

The May 2005 discharge monitoring reports were reviewed. The reports showed that no discharge occurred from any of the outfalls.

6. Disposal of Excess Spoil, Fills, Benches

Spoil is still being placed in Excess Spoil Pile #2. The permittee has an application submitted to the Division requesting the Expansion of this disposal area, Task ID #2223.

Permit Number: C0070035 Inspection Type: COMPLETE

Inspection Date: Wednesday, June 22, 2005 Page 4 of 4

7. Coal Mine Waste, Refuse Piles, Impoundments

Mining of the refuse pile is still taking place in pockets according to fuel needs at the power plant. The pile appeared stable with no visible hazards.

19. AVS Check

The Applicant/Violator System (AVS) was checked on May 26, 2005. No violations were listed. The entity ID showed 149252 Sunnyside Holdings I Inc 50% ownership and 149255 Sunnyside II LP 50% ownership, which correlates with the information contained in the approved Mining and Reclamation Plan (MRP).

20. Air Quality Permit

DAQO-702038-02 issued November 1, 2002, remains in effect. Air Quality Permit DAQE-691-99 issued August 13, 1999 was replaced by DAQO-702038-02. The permit was modified to allow the usage of a diesel generator on the power plant site. The Air Quality Permit covers both the power plant and mine site. The power plant site is not regulated by DOGM.

21. Bonding and Insurance

A Pledge and Escrow agreement dated January 4, 2002 is in place. This agreement is between Wells Fargo and the Division of Oil, Gas and Mining on behalf of SCA. SCA has invested \$1,747,000 in federally guaranteed Treasury Notes. The required bond amount is \$1,720,000.

Insurance for the site is under Federal Insurance Company, policy #3581-69-76. The policy was issued on August 1, 2004 and expires on August 1, 2005. The policy meets all the minimum requirements of the coal rules. No explosives coverage is noted on the insurance form. However, the MRP clearly identifies that all issues regarding explosives are not addressed, since explosives will not be used at the site. The certificate holder is listed as the State of Utah, Division of Oil, Gas and Mining.